



Degree of liquid entrainment is depending on density difference liquid / gas, viscosity, surface tension and vapour velocity.

Possible reasons for excessive vapour velocity:

- Vapour cross flow area too small selected
- Vapour cross flow area is reduced due to fouling / solids
- damaged valves, sharp edge sieve holes